


LDWSF
41.8.1
10-7-14

Sanga, Ravi

From: Dyer, Miles <mdyer@JorgensenForge.com>
Sent: Tuesday, October 07, 2014 3:38 PM
To: Ernst, William D; Sanga, Ravi; Bartus, Dave; Blankenship, Melissa
Cc: Tom Colligan
Subject: SSP covered in Black Plastic
Attachments: removed.txt; Black Plastic #3.jpg; Black Plastic #4.jpg; Black Plastic over SSP.JPG

Please see the attached pictures. The extracted SSP stored in the uplands area has been covered in black plastic. The black plastic was placed over the original 2 layers, creating a total of 3 layers of plastic, properly secured against natural elements.

Miles Dyer
Director, Environmental, Health and Safety Programs
Maintenance Director



Jorgensen Forge Corporation
8531 East Marginal Way South
Seattle, Washington 98108
Office Ph#: (206) 965-1352
Mobile: (740) 777-7808
Fax: (206) 357-1071
mdyer@jorgensenforge.com







